



Figure 4: Incidents with counter-measures in the control area of TenneT Germany (excluding voltage/reactive power problems)